

REPUBLIC OF PANAMA

Ministry of Finance and Treasury

Office of the Directorate of Merchant Marine Circular No. 81

Consular and Maritime Affairs

To: Shipowners/Operators of Panamanian MODUs and Class Societies
Subject: MARPOL 73/78 – Retention on Board of Oily Waste

Regulation 21 (Special requirements for drilling rigs and other platforms) of MARPOL 73/78 indicates in Subparagraph 'a':

"they shall be equipped as far as practicable with the installations required in Regulation 16 and 17 of this Annex"

On the basis of the subparagraph cited above this Administration has determined that it is impracticable for such units to install the equipment called for by Regulation 16 and, hence, prescribes that Drilling rigs, under its Flag, make provision to retain on board all machinery space oily waste in the waste oil tank for discharge in barrels to reception facilities

October, 2023 – Cancelled

July 1992

Inquiries concerning the subject of this Circular should be directed to:
Directorate of Consular and Maritime Affairs, New York Representative Office,
Republic of Panama, 1180 Avenue of the Americas, 23rd Floor
New York, New York 10036, U.S.A.